

THE
**FIRE
HOUSE** Group

FireGuard Limited

01709 579991

South Anston Fire Extinguishers

01709 584023

West Yorkshire Fire & Security

01134 264606

www.thefirehousegroup.co.uk
admin@thefirehousegroup.co.uk

Trent Valley Kart Club

FIRE EXTINGUISHER VISIT REPORT



Please Note: Only the Fireguard Limited company has the BAFE certification. If you are not under the Fireguard Company and require the BAFE certification, please advise us and we will swap the company that handles your account. This will not occur any additional fees.

British Standards recommends the Fire Extinguishers are
Services on an Annual Basis



- Fireguard
- S.A.F.E.
- W.Y.F.S.

The Fire House Group
Heritage House
Heritage Court
Hemingfield
Barnsley
S73 0HZ

FIRE EXTINGUISHER VISIT REPORT

PAGE 1 OF 4

COMPANY NAME	Trent Valley Kart Club	TECHNICIAN	Steve Shaw
SITE ADDRESS	P.F International Kart Circuit Brandon Grantham NG32 2AY	DATE	10/6/2022 12:07 pm
Contact Name & Number	Danielle/ Nigel/Clare 01632 626424 (james -site contact 07919367091)	QUOTED WORK (REF)	Q220863FG
		PO NUMBER	

WORK CARRIED OUT									
Equipment	Size	Extinguishers Serviced	Passed	Failed	Extinguishers Installed	Price of Extinguisher	Total cost of new Extinguishers	ID signs installed	Disposal
WATER	3LTR								
	6LTR				1				
	9LTR								
WATER WITH ADDITIVE	3LTR								
	6LTR								
	9LR								
CO2	2KG				1				
	5KG								
FOAM	1LTR								
	2LTR								
	3LTR								
	6LTR								
	9LTR								
WET CHEMICAL	2LTR								
	3LTR								
	6LTR								
POWDER	1KG								
	2KG				7				
	4KG								
	6KG								
	9KG								
MULTI CHEM	2LTR								
	3LTR								
	4LTR								
	6LTR								
F. BLANKET									
TOTALS		0	0	0	9		£0.00	0	0

EXTRA ITEMS PURCHASED			
QTY	ITEM	PPU	TOTAL
2	Fire Extinguisher ID signs in photoluminescent rigid plastic - landscape format (150 x 100)		
2	Branded Single Stand (RED) (These Can Be Connected Together To Create A Double Stand)		
TOTAL COST			£0.00

COSTINGS			
SERVICING COST PER UNIT		TOTAL COST	£0.00
FIXED SERVICING COST		TOTAL COST	
NEW FIRE EXTINGUISHERS		TOTAL COST	£0.00
ATTENDANCE FEE		TOTAL COST	
SIGNS COST PER UNIT		TOTAL COST	£0.00
DISPOSAL COST PER UNIT		TOTAL COST	£0.00
EXTRA ITEMS PURCHASED		TOTAL COST	£0.00

TOTAL AMOUNT PAYABLE	
TOTAL COST (EXCL. VAT)	£0.00
TOTAL COST (INC. VAT)	£0.00

PAYMENT METHOD			
Cash		Cheque	
		Account	<input checked="" type="checkbox"/>


ENGINEER COMMENTS
quoted work



- Fireguard
- S.A.F.E.
- W.Y.F.S.

The Fire House Group
 Heritage House
 Heritage Court
 Hemingfield
 Barnsley
 S73 0HZ

FIRE EXTINGUISHER VISIT REPORT

Are all extinguisher on stands or hung appropriately?	Is appropriate signage fitted?
Yes	Yes
No	No
N/A <input checked="" type="checkbox"/>	N/A <input checked="" type="checkbox"/>
Comments:	Comments:
Image: 	Image:


Is there a log book on site?
Yes
No
N/A <input checked="" type="checkbox"/>
Has the log book been completed?
Yes
No
N/A <input checked="" type="checkbox"/>
Comments:

SERVICING STANDARDS

The Firehouse Group have serviced the fire extinguishers and other fire protection equipment within the premises identified above in accordance with the requirements and frequencies indicated by BS5306 part 3 and refilled when required in accordance with BS5306 part 9.
 According to BS5306 part 3, it is the duty of the responsible person in the premises to inspect extinguishers at monthly intervals.
 P50 fire extinguishers are inspected in accordance with manufacturers recommendations.

WASTE TRANSFER INFORMATION

If any fire extinguishers are taken away from your site (identified in the disposal section), please see below the waste transfer and registration information.
 Waste Transfer Registration Number: CBDL285178. EWC Code: 16.05.05
 Some Fire Extinguishers are used for training and the remainder are broken down (the aluminium, plastic, steel & contents are all separated). Each component is collected by a 3rd party for recycling (powder is used for fertilizer). Copies of the 3rd parties waste transfer information is available upon request.

COMPLETION	
CUSTOMER NAME	nigel
CUSTOMER EMAIL ADDRESS	clare@tvkc.co.uk
ACCOUNT DEPARTMENT EMAIL ADDRESS	
DATE	10/6/2022 12:09 pm
SIGNATURE	
CUSTOMER COMMENTS/FEEDBACK	



- Fireguard
 S.A.F.E.
 W.Y.F.S.

The Fire House Group
Heritage House
Heritage Court
Hemingfield
Barnsley
S73 0HZ

FIRE EXTINGUISHER VISIT REPORT

PAGE 3 OF 4

Recommendations/Replacements - If not completed on the 1st visit				
	LOCATION/DESCRIPTION	ITEM	PPU	TOTAL

TOTAL COST OF RECOMMENDATIONS/REPLACEMENTS	
TOTAL COST (EXCL. VAT)	£0.00
TOTAL COST (INC. VAT)	£0.00

Have the replacements been discussed with the customer?	Yes	No
Comments:		

OTHER SERVICES AVAILABLE	
ITEM	TICK
Fire Risk Assessments	
Fire Alarm Installation / Service	
Emergency Light Installation / Service	
Fire Marshal Training	
Live Extinguisher Training	
Fire Suppression Installation / Service	
Fire Sprinkler Installation / Service	
Gas Systems Installation / Service	
Pat Testing	
Periodic Fixed Wire Testing	
CCTV Installation / Service	
Door Access Installation / Service	
Nurse Call Systems	



- Fireguard
- S.A.F.E.
- W.Y.F.S.

The Fire House Group
Heritage House
Heritage Court
Hemingfield
Barnsley
S73 0HZ

FIRE EXTINGUISHER VISIT REPORT

PAGE 4 OF 4

DATE: 10/6/2022 12:07 pm

TECHNICIAN: Steve Shaw

ASSET LIST:

FIRE EXTINGUISHER DTR DATES													
FIRE EXTINGUISHER	TOTAL	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
1KG POWDER													
2KG POWDER	10			1	2			7					
3KG POWDER													
4KG POWDER													
6KG POWDER													
9KG POWDER													
1LTR FOAM													
2LTR FOAM													
3LTR FOAM	1				1								
6LTR FOAM	1			1									
9LTR FOAM													
3LTR WATER	2				2								
6LTR WATER	1							1					
9LTR WATER													
2LTR WET CHEMICAL													
3LTR WET CHEMICAL													
6LTR WET CHEMICAL													
2KG CO2	2			1									1
5KG CO2													
FIRE BLANKET													

TOTAL NUMBER OF EXTINGUISHERS AND FIRE BLANKETS ON SITE:	17
---	----

FOR ENGINEERS USE ONLY	
<b style="color: red;">SITE ADDRESS & LOCATION NOTES Trent Valley Kart Club P.F International Kart Circuit Brandon Grantham NG32 2AY	<b style="color: red;">ENGINEERS COMMENTS



Certificate of Inspection

Fire Extinguishers

Date: 10/6/2022

Inspection carried out at:

Trent Valley Kart Club
P.F International Kart Circuit
Brandon
Grantham
NG32 2AY

Technicians Name: Steve Shaw

We hereby certify all the Fire Extinguishers at the above premises was inspected on the above date in accordance with BS5306/European Directives.

Routine Inspection by user:- BS5306-3:2017 Part 3 section (6) Recommends the user to regularly inspects all extinguishers, replacement charges etc. to make sure that they are in the proper position and are in working order.

The inspections should be carried out annually and you are advised to retain this certificate as proof of an inspection.



Extinguisher Type	On Site	Passed	Failed
Dry Powder	7	7	0
Water	1	1	0
Co2	1	1	0
Foam	0	0	0
Wet Chemical	0	0	0
Fire Blanket	0	0	0
Hose Reel	0	0	0
Multi Chem	0	0	0
D Class	0	0	0

The Fire House Group
Heritage House,
Heritage Court
Hemingfield,
Barnsley
S73 0HZ

Phone:
0844 693 1150

Email:
admin@thefirehousegroup.co.uk





DID YOU KNOW...

- Fire Alarm Systems should be serviced on a 6 monthly basis?
- Emergency Lighting should be serviced on an annual basis?
- Fire Risk Assessments should be conducted then reviewed on an annual basis?
- Periodic Inspections should be conducted on a 5 yearly basis?
- You should have employees that are trained fire marshals?
- Fire Extinguishers should be serviced on an annual basis?

DID YOU ALSO KNOW...

We can also offer the below:

- Fire Extinguisher Sales/Service
- Fire Alarm Installation/Service
- Emergency Lighting Installation/Service
- Fire Risk Assessments
- PAT Testing
- CCTV Installation/Maintenance
- Door Access Installation/Maintenance
- Gas Inspection Certificates
- Intruder Alarm Installation/Maintenance
- Fire Training

NEW SERVICES...

- Electrical Installations
- New Sockets
- New Lighting Installations
- Electrical Testing
- Fuse Board Upgrades/Changes
- Periodic Inspection

If you need assistance with any of these services please give us a call for a Free No Obligation Quotation on:

0844 693 1150

OR

Visit our website:

www.thefirehousegroup.co.uk