

Trent Valley Kart Club

FIRE EXTINGUISHER VISIT REPORT



| Fireguard |
|-----------|
| S.A.F.E. |

3.A.F.E.

W.Y.F.S.

The Fire House Unit 2 Swinton Bridge Workshops, Rowms Lane, Swinton, Rotherham, S64 8AE

FIRE EXTINGUISHER VISIT REPORT

PAGE 1 OF 3

| COMPANY NAME | Trent Valley Kart Club | TECHNICIAN | Steve Shaw |
|--------------|--------------------------------|-------------------|--------------------|
| SITE ADDRESS | P.F International Kart Circuit | DATE | 4/10/2019 12:00 pm |
| | | CONTRACT SERVICE | > |
| | | NEW CUSTOMER | |
| | Grantham | QUOTED WORK (REF) | |
| | NG32 2AY | PO NUMBER | |
| | | | |

| WORK CARRIED OUT | | | | | | | | | | OTHER SERVICES AVAILABLE | |
|------------------|------|---------------------------|--------|--------|----------------------------|-----|--------------------------|----------------------|-------------------|--------------------------|---|
| EQUIPMENT | SIZE | EXTINGUISHERS SERVICED | PASSED | FAILED | EXTINGUISHERS INSTALLED | R/N | PRICE OF EXTINGUISHER | TOTAL COST OF NEW | ID SIGN INSTALLED | DISPOSAL | ITEM TICK |
| WATER | 3LTR | | | | | | | | | | Fire Risk Assessments |
| | 6LTR | | | | | | | | | | Fire Alarm Installation / Service |
| | 9LTR | | | | | | | | | | Emergency Light Installation / Service |
| WATER WITH | 3LTR | | | | 2 | N | £44.49 | £88.98 | 2 | | Fire Marshall Training |
| ADDITIVE | 6LTR | | | | | | | | | | Live Extinguisher Training |
| | 9LR | | | | | | | | | | Fire Suppression Installation / Service |
| CO2 | 2KG | 2 | 2 | 0 | | | | | 1 | | Fire Sprinkler Installation / Service |
| | 5KG | | | | | | | | | | Gas Systems Installation / Service |
| FOAM | 1LTR | | | | | | | | | | Pat Testing |
| | 2LTR | | | | | | | | | | Periodic Fixed Wire Testing |
| | 3LTR | | | | 1 | N | £43.20 | £43.20 | 1 | | CCTV1nstallation/Service |
| | 6LTR | | | | | | | | | | Door Access Installation / Service |
| | 9LTR | | | | | | | | | | Nurse Call Systems |
| WET | 2LTR | | | | | | | | | | |
| CHEMICAL | 3LTR | | | | | | | | | | CUSTOMER INFO |
| | 6LTR | | | | | | | | | | Telephone Number: |
| POWDER | 1KG | | | | | | | | | | 01632 626 424 |
| | 2KG | 10 | 8 | 2 | 2 | N | £29.13 | £58.26 | | | James (Site Contact) - 07919 367 091 |
| | 4KG | | | | | | | | | | Contact Name: |
| | 6KG | 2 | 2 | 0 | | | | | | | Nigel Edwards / Clare |
| | 9KG | | | | | | | | | | Niger Edwards / Clare |
| MULTI CHEM | 2LTR | | | | | | | | | | Accounts Email Address: |
| | 3LTR | | | | | | | | | | 1 |
| | 4LTR | | | | | | | | | |] |
| | 6LTR | | | | | | | | | | Further Information: |
| F. BLANKET | | | | | | | | | | | TRENT001 |
| HOSE REEL | | | | | | | | | | | <u> </u> |
| D CLASS | | | | | | | | | | | <u> </u> |
| TOTALS | | 14 | 12 | 2 | 5 | | | £190.44 | 4 | 0 | |

| | EXTRA ITEMS PURCHASED | | | ENGINEERS COMMENTS |
|------------|-----------------------|----------|-------------|--------------------|
| QTY | ITEM | PPU | TOTAL | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | <u> </u> | |
| | | | | |
| | | | | |
| TOTAL COST | | <u> </u> | £0.00 | |

| | C | USTINGS | |
|-------------------------|--------|------------|---------|
| SERVICING COST PER UNIT | | TOTAL COST | £0.00 |
| FIXED SERVICING COST | £90.00 | TOTAL COST | £90.00 |
| NEW FIRE EXTINGUISHERS | | TOTAL COST | £190.44 |
| ATTENDANCE FEE | | TOTAL COST | |
| SIGNS COST PER UNIT | £2.28 | TOTAL COST | £9.12 |
| DISPOSAL COST PER UNIT | | TOTAL COST | £0.00 |
| EXTRA ITEMS PURCHASED | | TOTAL COST | £0.00 |

| PAYMENT METHOD | | | | |
|----------------|-----------|--|--|--|
| CASH | | | | |
| CHEQUE | | | | |
| ACCOUNT | \ <u></u> | | | |

| TOTAL AMOUNT PAYABLE | |
|------------------------|---------|
| TOTAL COST (EXCL. VAT) | £289.56 |
| TOTAL COST (INC. VAT) | £347.47 |



S.A.F.E.

W.Y.F.S.

The Fire House Unit 2 Swinton Bridge Workshops, Rowms Lane, Swinton, Rotherham, S64 8AE

FIRE EXTINGUISHER VISIT REPORT

PAGE 2 OF 3

| RECOMMENDATIONS/REPLACEMENTS - IF NOT COMPLETED ON THE 1ST VISIT. | | | | | | | | |
|---|-------------------------|--|-----------------|---------------|--|--|--|--|
| QTY | LOCATION/DESCRIPTION | ITEM | PPU | TOTAL | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | • | | | | | |
| | | TOTAL COST OF RECOMMENDATIONS/REPLACEMENTS | T | | | | | |
| TOTAL | COST (EXCL. VAT) | | £0 | .00 | | | | |
| ΤΟΤΔΙ | COST (INC. VAT) | | £0 | .00 | | | | |
| 101712 | cost (intel titil) | | l | | | | | |
| | | SERVICING STANDARDS | | | | | | |
| The F | | ners and other fire protection equipment within the premises identified above in accordance with the | requirements an | d frequencies | | | | |
| | | ated by BS5306 part 3 and refilled when required in accordance with BS6643 part 1. 3, it is the duty of the responsiable person in the premises to inspect extinguishers at monthly inten | vals. | | | | | |
| | 7.000.0g to 2000 part | | | | | | | |
| | | COMPLETION | | | | | | |
| | MER NAME | Clare | | | | | | |
| DATE | MER EMAIL ADDRESS | Danielle@tvkc.co.uk | | | | | | |
| DATE | | 4/10/2019 12:00 pm | | | | | | |
| | | | | | | | | |
| SIGNA | TURE | | | | | | | |
| | · • · · · | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| CLISTO | MER COMMENTS/FEEDBACK | | | | | | | |
| 20310 | MEN COMMENTO/ I ELDUACK | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |



| | | gu | _ | |
|--------|----|----|---|---|
| - II-I | re | ØH | a | " |
| | | ьч | м | • |

W.Y.F.S.

S.A.F.E

The Fire House Unit 2 Swinton Bridge Workshops, Rowms Lane, Swinton, Rotherham, S64 8AE

FIRE EXTINGUISHER VISIT REPORT

PAGE 3 OF 3

DATE:4/10/2019 12:00 pm TECHNICIAN: Steve Shaw ASSET LIST:

| DATE:4/10/2019 12:00 pm | TEC | CHNICIAN: | Steve Sha | | | | ASSET LIS | iT: | | | | | |
|-------------------------|--------|-----------|-----------|-----------|-------|-------|-----------|------|------|------|------|------|------|
| | | | | XTINGUISI | | | | | | | | | |
| FIRE EXTINGUISHER | TOTAL | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 |
| 1KG POWDER | | | | | | | | | | | | | |
| 2KG POWDER | 10 | | | 2 | 2 | 3 | 1 | 2 | | | | | |
| 3KG POWDER | | | | | | | | | | | | | |
| 4KG POWDER | | | | | | | | | | | | | |
| 6KG POWDER | 2 | | | 1 | 1 | | | | | | | | |
| 9KG POWDER | | | | | | | | | | | | | |
| 1LTR FOAM | | | | | | | | | | | | | |
| 2LTR FOAM | | | | | | | | | | | | | |
| 3LTR FOAM | 1 | | | | | | | 1 | | | | | |
| 6LTR FOAM | | | | | | | | | | | | | |
| 9LTR FOAM | | | | | | | | | | | | | |
| 3LTR WATER | 2 | | | | | | | 2 | | | | | |
| 6LTR WATER | | | | | | | | | | | | | |
| 9LTR WATER | | | | | | | | | | | | | |
| 2LTR WET CHEMICAL | | | | | | | | | | | | | |
| 3LTR WET CHEMICAL | | | | | | | | | | | | | |
| 6LTR WET CHEMICAL | | | | | | | | | | | | | |
| 2KG CO2 | 2 | | | | 1 | | 1 | | | | | | |
| 5KG CO2 | | | | | | | | | | | | | |
| FIRE BLANKET | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| TOTAL NUMBER OF | EXTING | GUISHE | RS AN | D FIRE | BLANK | ETS O | N SITE: | 17 | | | | | |

TOTAL NUMBER OF EXTINGUISHERS AND FIRE BLANKETS ON SITE: 17

FOR ENGINEERS USE ONLY

| TON ENGINEERS OUT ONE | | | | | | |
|--|--------------------|--|--|--|--|--|
| SITE ADDRESS & LOCATION NOTES Trent Valley Kart Club | ENGINEERS COMMENTS | | | | | |
| P.F International Kart Circuit | | | | | | |
| Brandon | | | | | | |
| Grantham | | | | | | |
| NG32 2AY | | | | | | |
| | | | | | | |
| | | | | | | |



Certificate of Inspection Fire Extinguishers

Date: 4/10/2019

Inspection carried out at:

Trent Valley Kart Club P.F International Kart Circuit

Brandon

Grantham

NG32 2AY

We hereby certify all the Fire Extinguishers at the above premises was inspected on the above date in accordance with BS5306/European Directives.

Routine Inspection by user:- BS5306-3:2017 Part 3 section (6) Recommends the user to regularly inspects all extinguishers, replacement charges etc. to make sure that they are in the proper position and are in working order.

The inspections should be carried out annually and you are advised to retain this certificate as

proof of an inspection.



| Extinguisher Type | On Site | Passed | Failed |
|----------------------|---------|--------|--------|
| Dry Powder | 12 | 12 | 0 |
| Water | 2 | 2 | 0 |
| Co2 | 2 | 2 | 0 |
| Foam | 1 | 1 | 0 |
| Wet Chemical | 0 | 0 | 0 |
| Fire Blanket | 0 | 0 | 0 |
| Hose Reel | 0 | 0 | 0 |
| Multi Chem | 0 | 0 | 0 |
| D Class | 0 | 0 | 0 |

The Fire House Group

S64 8AE

Unit 2 Swinton Bridge Workshops Rowms Lane Swinton Rotherham

Phone:

0844 693 1150

Email:

admin@thefirehousegroup.co.uk



DID YOU KNOW...

- Fire Alarm Systems should be serviced on a 6 monthly basis?
- Emergency Lighting should be serviced on an annual basis?
- Fire Risk Assessments should be conducted then reviewed on an annual basis?
- Periodic Inspections should be conducted on a 5 yearly basis?
- You should have employees that are trained fire marshals?
- Fire Extinguishers should be serviced on an annual basis?

DID YOU ALSO KNOW...

We can also offer the below:

- Fire Extinguisher Sales/Service
- Fire Alarm Installation/Service
- Emergency Lighting Installation/Service
- Fire Risk Assessments
- PAT Testing

- CCTV Installation/Maintenance
- Door Access Installation/Maintenance
- Gas Inspection Certificates
- ➤ Intruder Alarm Installation/Maintenance
- Fire Training

NEW SERVICES...

- Electrical Installations
- New Sockets
- New Lighting Installations

- Electrical Testing
- Fuse Board Upgrades/Changes
- Periodic Inspection

If you need assistance with any of these services please give us a call for a Free No Obligation Quotation on:

0844 693 1150

OR

Visit our website:

www.thefirehousegroup.co.uk