



British Kart  
Championships

Event Bulletin

Rotax & KZ2

Kimbolton 12-14 May 2023.

## Event Bulletin 04

### Clarification – Rotax Cylinder Protection Plate

5.4.1 Distance of Exhaust Valve Flange at Cylinder to Piston Turn crankshaft until the piston just closes the exhaust port. Insert the exhaust valve gauge (ROTAX 277030) as shown in the picture until it stops at the flange. At the contact area between exhaust valve gauge (ROTAX 277030) and the flange of the cylinder, a feeler gauge 0.05mm must not fit between the gauge and the flange. The measurement must be performed outside the exhaust valve contact area indicated in red. **Where the plate is not present the measurement of 0.25 must be respected.** The measurement must be performed outside the exhaust valve contact area indicated in red on the Motorsport UK Rotax Max technical regulations.

Issued to take account of the optional fitment of the cylinder protection plate.

Signed Race Director: Nigel Edwards

13<sup>th</sup> May 2023

16.45hrs